REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH

DEVELOPMENT

DOUGLAS AIRCRAFT COMPANY

Internal Mail Code 211-46

3855 Lakewood Blvd.

Long Beach, CA 90846

Attention: Robert M. Tomko

SAMPLE

CLIENT

Monthly Storm Drain Inspection

September, 1989

P.O. #T & M-23465-C

INVESTIGATION

As requested by the CRWQCB for NPDES permit numbers CA0001406 and CA0001414



14201 FRANKLIN AVENUE TUSTIN, CALIFORNIA 92680 AREA CODE 714 • 730-6239 AREA CODE 213 . 225-1564 CABLE: TRUELABS

Sept. 28, 1989

DATE

Sept. 8, 1989 RECEIVED


LABORATORY NO.

34596

RESULTS

A representative of Truesdail Laboratories, Inc., tested the strom drain discharge on September 8, 1989, at the Douglas Long Beach (003) and Torrance facilities. The discharge was tested for flow rate, pH, and temperature. The results are as follows:

Sample I.D.	Date	Time	Flow-gpd	$\underline{\text{Temp}}, \underline{0}_{\underline{F}}$	pH, Units
Long Beach (003)	9-08-89	1:30	67,392	71	8.2
Torrance	9-08-89	10:30	513	70	7.6



Respectfully submitted, TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor

Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter